

Terrazzo Cracking



Deval Patrick
Governor

Timothy P. Murray
Lieutenant Governor

Bernard Cohen
Secretary

Luisa Paiewonsky
Commissioner

August 2007

Office of Transportation Planning

SPRII 03.07.11

Technical Report Document Page

1. Report No. SPRII 03.07.11	2. Government Accession No. N/A	3. Recipient's Catalog No. N/A	
4. Title and Subtitle Terrazzo Cracking		5. Report Date August 2007	
		6. Performing Organization Code N/A	
7. Author(s) Scott A. Civjan, Ph.D., P.E. Ray K. Mann, M. Arch, R.A. Michael J. Mitchell		8. Performing Organization Report No. UMTC-07-01	
9. Performing Organization Name and Address University of Massachusetts Transportation Center 214 Marston Hall 130 Natural Resources Road Amherst, MA 01003		10. Work Unit No. (TRAIS) N/A	
		11. Contract or Grant No. ISA#4MS9793 Task #11	
12. Sponsoring Agency Name and Address Executive Office of Transportation and Public Works Office of Transportation Planning 10 Park Plaza Boston, MA 02116		13. Type of Report and Period Covered Final Report 2006-2007	
		14. Sponsoring Agency Code N/A	
15. Supplementary Notes			
<p>16. Abstract</p> <p>Terrazzo is generally a versatile, durable and low maintenance flooring material. However, widespread terrazzo cracking has occurred in several elevated walkway bridge structures at Logan International Airport. Cracking was broadly defined to include separation of terrazzo from divider strips and deterioration from impact loadings. Cracking typically occurred shortly after opening of the walkways, but some new cracking has appeared after a period of time in service. Installation techniques and construction methods were altered during construction of individual pedestrian bridge structures to mitigate problems as they were discovered and some repairs have been completed. While the extent of cracking varies in the elevated walkways some cracking has occurred in all elevated walkways.</p> <p>The objectives of this research project were to determine the causes of terrazzo cracking at the walkway bridge structures at Logan International Airport develop specifications for terrazzo installation to prevent cracking in future structures and develop guidelines for repairing existing cracks. In order to provide a means for impacting current practice, QA/QC and implementation procedures were also addressed. This report also serves as documentation of advancements in terrazzo construction practice for terrazzo implemented in recent Massachusetts Port Authority projects.</p>			
17. Key Word Terrazzo, Cracking, Elevated Walkway, Repair		18. Distribution Statement Document available through the sponsor organization	
19. Security Classif. (of this report) N/A	20. Security Classif. (of this page) N/A	21. No. of Pages 128	22. Price N/A