

# Renewable Energy Research Laboratory

Department of Mechanical and Industrial Engineering University of Massachusetts 160 Governor's Drive Amherst, MA 01003-9265 Phone: 413-545-4359 Fax: 413-577-1301 www.ceere.org/rerl rerl@ecs.umass.edu



### Data Update for Bishop and Clerks, Nantucket Sound, MA July 2006

Prepared for Massachusetts Technology Collaborative 75 North Drive, Westborough, MA 01581

By Chris Elkinton

## **Monthly Data Summary for July 2006**

This update summarizes the monthly data results for the Bishop and Clerks monitoring site in Nantucket Sound, MA, at 41° 34′ 27.6″ N, 70° 14′ 59.5″ W (NAD 83). More information on the sensors and site can be found at www.ceere.org/rerl/rerl resourcedata.html.

	Wind Speed			Prevailing
Height	Mean [m/s]	Max [m/s]	Turbulence Intensity	Wind Direction
15 m	n/a	n/a	n/a	n/a

The data recorded at this site are available at the Renewable Energy Research Laboratory web site: <a href="www.ceere.org/rerl/rerl\_resourcedata.html">www.ceere.org/rerl/rerl\_resourcedata.html</a>. It is important to note that summary data are only reported when the monthly net data recovery (see below) is at least 90%. This requirement ensures that the values reported here are comparable with values from other months.

Additional information about interpreting the data presented in this report can be found in the Fact Sheet, "Interpreting Your Wind Resource Data," produced by RERL and the Massachusetts Technology Collaborative (MTC). This document is found through the RERL website:

www.ceere.org/rerl/about wind/RERL Fact Sheet 6 Wind resource interpretation.pdf.

#### **Data Recovery**

All raw wind data are subjected to a series of tests and filters to identify data that are faulty or corrupted. The gross percentage of data recovered (ratio of the number of raw data points received to data points expected) and net data recovered (ratio of raw data points which passed all QA control tests to data points expected) are shown below.

Gross Data Recovered [%]	58.89
Net Data Recovered [%]	58.45


# **Maintenance Issues and Changes to Site Configuration**

The following maintenance/equipment problems occurred during July 2006, and the following corrective action was taken:

- The memory card in the data logger reached its capacity on July 4.
- The data logger was replaced on July 17 in order to fix problems with communication with the site. There is a gap in the data from July 4 to July 17.

## **Monthly Data Time Series**

Seen below is a graph of wind speed at Bishop and Clerks for the month of July 2006, measured at the anemometer height of 15 m.



Plot by DQMS3 - dqms@dqms.com