



# Renewable Energy Research Laboratory

Department of Mechanical and Industrial Engineering  
University of Massachusetts  
160 Governor's Drive  
Amherst, MA 01003-9265

Phone: 413-545-4359  
Fax: 413-577-1301  
www.ceere.org/rerl  
rerl@ecs.umass.edu



## Data Update for Mt. Tom, Holyoke, MA May 2006

Prepared for  
Massachusetts Technology Collaborative  
75 North Drive, Westborough, MA 01581

By Melissa Ray

### Monthly Data Summary for May 2006

This update summarizes the monthly data results for the Mt. Tom monitoring site in Holyoke, MA, at 42° 14' 59.2" N, 72° 38' 42.2" W (NAD 27). More information on the sensors and site can be found at [http://www.ceere.org/rerl/rerl\\_resourcedata.html](http://www.ceere.org/rerl/rerl_resourcedata.html).

Height	Wind Speed				Prevailing Wind Direction	Power Law Shear Exponent
	Mean [m/s]	Max [m/s]	Turbulence Intensity	Data Good [%]		
24 m	4.9	14.4	0.28	99.8	22.5°, NNE	0.40
37 m	5.8	16.2	0.22	100.0	--	

The data reported here are only based on the percentages of good data indicated; missing data may skew these values. The 37 m vane failed in August 2005, so the 37 m prevailing wind direction is not reported. For these data, the 24 m vane data have been used in the 37 m icing test definition.

The data can be found at the Renewable Energy Research Laboratory web site:  
[http://www.ceere.org/rerl/rerl\\_resourcedata.html](http://www.ceere.org/rerl/rerl_resourcedata.html).

### Data Recovery

All raw wind data are subjected to a series of tests and filters to identify data that are faulty or corrupted. The gross percentage of data recovered (ratio of the number of raw data points received to data points expected) and net data recovered (ratio of raw data points which passed all QA control tests to data points expected) are shown below.

Gross Data Recovered [%]	100.00
Net Data Recovered [%]	99.36


The high gross and net data recovery indicate that the logger and sensors are performing well.

### **Maintenance Issues and Changes to Site Configuration**

No maintenance or equipment problems occurred during May 2006, however the failed vane at the 37 m level is scheduled to be replaced.

### **Monthly Data Time Series**

Seen below is a graph of wind speed at Mt. Tom for the month of May 2006, at the anemometer height of 37 m.



*Plot by DQMS3 - dqms@dqms.com*